B.R. No: 662/Date: 29/03/2014

Inspection report for the work of : Annual Maintenance of borewell of Abbigere & Shettyhalli in Dasarahalli Zone

By

Sri. *G.M. Muniyappa*

Inspection Report

Name of Work		Annual **Maintenance of borewell of Abbigere & Shettyhalli in Dasarahalli Zone**
Work Order	:	No. EE/DD/WO/ 158/13-14, Dated: 12/12/2013
Agency	:	S. Prakash
B.R. No & Dated	:	662/Date: 29/03/2014
Bill Amount	:	Rs. 1460640
Job Code	:	012-13-000039
P. Code	:	P1771

Date of Inspection:— The above said Work Maintenance of Bore wells of Abbigere and Shettihalli in Dasarahalli zone, has been done by the Concerned AE.

The above said work has been inspected along with the Concerned AE.

The Water Supply to the Residents of the Vicinity of the Bore Wells is running Smoothly.

The Registers pertaining to the Repairs of Pump, Motor and Bore wells is Verified. The Concerned File is Verified pertaining to the "B BOOM"

The Work done is Satisfactory

Ravi. N.K.
AEW-12

ಪಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ,

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು-57

Name of Work : Annexure Maintenance of borewell of Abbigere & Shettyhalli in Dasarahalli Zone

Ravi.N.K.

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ,
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು-57